



RENAULT CLIO: 1KPL025

Vinnumber:	VF15RJL0H53062243	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	10/06/2015	Fiscalpower:	
Expertise Mileage:	100018	Power Kw:	66
Bodytype:	Hatchback	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2504
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/65/15/92 V Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1361,52
--------------------------	----------------

Bonnet, Chemical polution, LI - Repair and paint (complete)	232,06
--	---------------





Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14




Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Roof, Dent(s), LI - Repair and paint (complete) 481,20



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68



Door R R, Bad repair, Acceptable 0,00



Wheel cover F L, Deformed / Strained, E - Replace 24,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display