



Peugeot Boxer: 1GBW280

Vinnumber:	VF3YDPMFC12A21999	Versionname:	
First Registrationdate:	7/01/2016	Fiscalpower:	
Expertise Mileage:	132927	Power Kw:	130
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV24
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Rear parking sensors	
GPS storage	HD	Type of Tow bar	Tow bar fixed
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/75/16/120 R Steel			
Summer tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	No	Jack	Yes
-----------------------	-----------	------	------------

Total cost ex VAT	1042,86
-------------------	----------------

A-Pillar left, Deformed / Strained, LI - Repair and paint (complete)	172,23
--	---------------



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Door catch F L, Strained , P - Check 0,00

No pictures to display

Rocker panel inner F L, Scratch(es), Forfeit 110,00



Interior, Worn, Acceptable 0,00



Wing trim R L, Deformed / Strained, E - Replace 69,00



Trunk door panel R, Broken, E - Replace 45,00



Wheel cover R L, Missing, E - Replace 22,50



Roof, Dent(s), LI - Repair and paint (complete) 361,13



Tyre R R, Flat, E - Replace 105,00



Sill F L, Deformed / Strained, E - Replace

99,20



Interior, Dirty, Cleaning

48,00



Wing moulding F L, Broken, E - Replace

10,80

