


SKODA SUPERB: RN6097

Vinnumber:	TMBAG9NP3J7520048	Versionname:	1.6 CRTDI 88kW DSG7 Style
First Registrationdate:	6/09/2017	Fiscalpower:	
Expertise Mileage:	92953	Power Kw:	88
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4727
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats R heated	
Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	215/52/17/98 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	74,00
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	74,00



Wing F R, Scratch(es), 67 - Polish

0,00

No pictures to display