



**SKODA FABIA COMBI: 1KKF341**

Vinnumber:	<b>TMBJJ6NJ8FZ070209</b>	Versionname:	<b>1.4 CRTDI 66KW AMBITION</b>
First Registrationdate:	<b>19/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>162031</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 14200 KM</b>	Parking lot:	<b>2212</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F		Central consol F	
Type of headlighting	<b>Headlighting Halogen</b>	Luggage cover	
Type of GPS	<b>No GPS</b>	Rear parking sensors	
Type of Lining	<b>Lining fabrics</b>	Type of Tow bar	<b>No Tow bar</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>185/60/15/84 T Steel</b>				
Summer tyres:	Fr.L.	<b>Hankook: 5 mm</b>	Fr.R.	<b>Hankook: 5 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>958,00</b>
-------------------	---------------

Door seal F L, Damaged, E - Replace	<b>48,00</b>
-------------------------------------	--------------



Wing R R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------



Door panel R R, Scratch(es), Acceptable

0,00



Seat cover F R, Stain, Acceptable

0,00



Seat cover R, Stain, Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Seat cover F L, Stain, Cleaning

25,00



Outer door handle F R, Scratch(es), Acceptable

0,00



Dashboard, Scratch(es), E - Replace

600,00



Wheel cover F R, Scratch(es), Acceptable

0,00



Bumper F, Scratch(es), It - Spot repair

115,56



Windscreen, Stone chip(s), P - Check

0,00

