



**SKODA Octavia: 1CM361**

Vinnnumber:	<b>TMBHT21Z5C2109954</b>	Versionname:	<b>OCTAVIA COMBI Ambiente DPF 105PK</b>
First Registrationdate:	<b>3/01/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>127901</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1129</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Type of headlighting		Type of Tow bar	<b>No Tow bar</b>
Type of GPS	<b>Headlighting Halogen</b>		
Type of Lining	<b>GPS big screen color</b>		
Type of climate control	<b>Lining fabrics</b>		
	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L. <b>Uniroyal: 6 mm</b>	Fr.R. <b>Uniroyal: 6 mm</b>	
	Re.L. <b>Bridgestone: 6 mm</b>	Re.R. <b>Bridgestone: 6 mm</b>	

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	0,00
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bad repair, Acceptable	0,00

