



**VW Golf: 1KTZ195**

Vinnnumber:	<b>WVWZZZAUZFW610570</b>	Versionname:	
First Registrationdate:	<b>21/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>179292</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>TRU12</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F
GPS storage	<b>SD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Adaptive cruise control		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>NOT OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>2032,42</b>
-------------------	----------------

Bumper F, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 404,20



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Scratch(es), E - Replace 30,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Le - Replace and paint 946,92



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Engine, Not functioning (well), P - Check 0,00



Maintenance book, Missing, E - Replace 0,00



Bodywork, Dirty, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 200,00

