



VOLKSWAGEN Golf: 1HYP539

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WVWZZZAUZFP550423 | Versionname: | GOLF VAR Trendline 90PK |
| First Registrationdate: | 30/10/2014 | Fiscalpower: | |
| Expertise Mileage: | 158079 | Power Kw: | 66 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2224 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-------------------|
| Radio CD | Central consol F | |
| Windows electric F | Luggage cover | |
| Windows electric R | Front parking sensors | |
| Cruise Control | Rear parking sensors | |
| Steering wheel multifunctional | Type of Tow bar | No Tow bar |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
| | 195/65/15/91 H Steel | | | |
| Summer tyres: | Fr.L. | Vredestein: 6 mm | Fr.R. | Vredestein: 6 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|

| | |
|-----------------------------------|------|
| Total cost ex VAT | 0,00 |
| Wing R L, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |