



VOLKSWAGEN UP! 1TU0790

Vinnumber:	WVWZZZAAZH0073517	Versionname:	
First Registrationdate:	14/02/2018	Fiscalpower:	
Expertise Mileage:	19376	Power Kw:	44
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

165/70/14/81 T Steel				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	914,12
Wing R R, Scratch(es), LI - Repair and paint (complete)	246,56





Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Instruction book, Missing, E - Replace 0,00

No pictures to display

Fuel cap cover, Broken, E - Replace 74,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44

