



VOLVO V60: UJ9012

Vinnnumber:	YV1FW79C1G1292536	Versionname:	2.0 D3 VOLVO OCEAN RACE
First Registrationdate:	7/07/2015	Fiscalpower:	
Expertise Mileage:	168335	Power Kw:	110
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3119
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/40/18/97 Y LightMetal				
Summer tyres:	Fr.L.	Vredestein: 3 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1033,56
-------------------	---------

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper F R, Scratch(es), It - Spot repair 115,56



Rearview mirror R complete, Broken, E - Replace 168,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear window, Scratch(es), E - Replace 370,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

