



VOLVO XC60: 1KSA323

Vinnumber:	YV1DZA8C1G2798190	Versionname:	2.0 D4 2WD MOMENTUM
First Registrationdate:	19/06/2015	Fiscalpower:	
Expertise Mileage:	149922	Power Kw:	140
Bodytype:	SUV	Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	Tow bar fixed
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Summer tyres:	Fr.L.	Fulda: 8 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Maintenance book, Missing, E - Replace	0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Bumper F, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display