


BMW 4 GRAN COUPE: 1PCL545

Vinnumber:	WBA4E71040G549554	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	3/06/2016	Fiscalpower:	
Expertise Mileage:	90959	Power Kw:	100
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4427
Battery functioning	Yes		
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/18/91 Y LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	1842,24
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	350,16





Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Cigar lighter, Missing, E - Replace

21,60



Alloy rim F R polished, Scratch(es), E - Replace

277,44



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R R polished, Scratch(es), E - Replace

277,44



Model badge R, Incomplete, E - Replace

25,00



Floor covering F L, Hole, E - Replace

264,00



Alloy rim F L polished, Scratch(es), E - Replace

277,44



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00

