



RENAULT CLIO: 1KNF175

Vinnumber:	VF15RJL0H53062258	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	84728	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 V Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 453,86

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Seat cover F R, Stain, Cleaning 25,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Wheel cover R R, Broken, E - Replace 24,00



Wheel cover R L, Scratch(es), E - Replace 24,00



Wheel cover F R, Scratch(es), E - Replace 24,00



Sill F L, Broken, E - Replace 52,52



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Tyre R R, Tear, Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display