


AUDI A3: 1GMZ368

Vinnumber:	WAUZZ8V2EA151714	Versionname:	A3 SB Ambiente 105PK
First Registrationdate:	14/03/2014	Fiscalpower:	
Expertise Mileage:	101488	Power Kw:	77
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Body color	GRIS
Transmission:	Front	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Maintenance	5900 KM 201 DAGEN	Parking lot	1524
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	708,60
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Chemical pollution, Acceptable

0,00

No pictures to display

Outer door handle F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

