


AUDI Q3: 1KRD104

Vinnumber:	WAUZZZ8U0FR047104	Versionname:	2.0 TDI 100KW
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	75595	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/5/17/99 V LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			597,06
Door R R, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Rear spoiler, Chemical polution, LI - Repair and paint (complete)			115,56



Roof pillar L, Chemical polution, 67 - Polish	0,00
---	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Tailgate, Chemical polution, 67 - Polish	0,00
--	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display