



AUDI Q5: 1KUK793

Vinnumber:	WAUZZZ8R7FA144486	Versionname:	2.0 TDI 110KW
First Registrationdate:	7/07/2015	Fiscalpower:	
Expertise Mileage:	95094	Power Kw:	110
Bodytype:	SUV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 3 mm	Fr.R.	Fulda: 3 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	1281,89
-------------------	----------------

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Tyre repair kit, Missing, E - Replace	252,64
---------------------------------------	---------------



Door R R, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	74,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), Smart repair

110,64



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

264,21



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84

