



AUDI A6 AVANT: 1KBD937

Vinnumber:	WAUZZZ4G6FN065243	Versionname:	2.0 TDI ULTRA 110KW S TRONIC S LINE
First Registrationdate:	24/03/2015	Fiscalpower:	
Expertise Mileage:	159416	Power Kw:	110
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1505
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
Sport seats	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

Summer tyres:	245/45/18/100 W LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	539,16
Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), 67 - Polish	0,00
No pictures to display	
Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display


Wing R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

