


AUDI A4 AVANT: 1KNE197

Vinnumber:	WAUZZZ8K0FA131632	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	2/06/2015	Fiscalpower:	
Expertise Mileage:	76193	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4816
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar removable
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1007,76
Rearlight R , Broken, E - Replace	114,00



Bumper R, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), It - Spot repair 115,56



Engine, Not functioning (well), P - Check 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Alloy rim F L, Scratch(es), I - Repair 100,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 0,00

No pictures to display

Wing R R, Dent(s), LI - Repair and paint (complete) 308,20



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display