



AUDI A6: 1HAZ413

Vinnumber:	WAUZZZ4G2EN165970	Versionname:	A6 AVANT S-line 136PK
First Registrationdate:	6/06/2014	Fiscalpower:	
Expertise Mileage:	153975	Power Kw:	100
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2209
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.
	Re.L.	Uniroyal: 6 mm	Re.R.

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	698,32
-------------------	--------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------




Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Rear window, Scratch(es), Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00





Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display