



BMW 5 BERLINE: 1KFJ975

Vinnumber:	WBA5E31060D672786	Versionname:	2.0 518D (100KW)
First Registrationdate:	21/04/2015	Fiscalpower:	
Expertise Mileage:	61753	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Body color:	BLAUW
Transmission:	Back	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Maintenance:	6000 KM	Oil level:	OK
Maintenance:	OK	Parking lot:	1333
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
GPS storage		Seats electric F L	
GPS storage	HD	Seats electric F R	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT **688,16**

Alloy rim 5 L - Scratch(es) - Acceptable 0,00

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (partial) 115,56



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bad repair, P - Check 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), I - Repair 100,00



Wing R L, Bad repair, P - Check 0,00



Wing F L, Bad repair, P - Check 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete) 372,60



Door R L, Bad repair, P - Check 0,00



Alloy rim R R, Scratch(es), I - Repair 100,00



