



BMW 4 COUPE: 1KPH414

Vinnumber:	WBA4P710X0K312834	Versionname:	2.0 420D (120KW)
First Registrationdate:	9/06/2015	Fiscalpower:	
Expertise Mileage:	77625	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2731
Battery functioning:	Yes		
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/91 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1822,05
Backrest cover F L, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Hail damage, PDR - Hail		0,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 468,60



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Engine protective plate, Broken, E - Replace 99,71



Door frame F L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R R, Stain, Cleaning 25,00



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 478,02



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Door F L, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

350,16




Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Hail damage, PDR - Hail

0,00



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display