



BMW 3 GRAN TURISMO: ZT4415

Vinnumber:	WBA8Y51020G576023	Versionname:	2.0 318D (110KW) GRAN TURISMO
First Registrationdate:	27/10/2021	Fiscalpower:	
Expertise Mileage:	163537	Power Kw:	110
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining Alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/45/18/99 W LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	582,76
Seat cover R, Stain, Cleaning	25,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Tyre F L, Tear, E - Replace

153,60



Ignition key, Missing, E - Replace

150,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display