



**BMW 3 TOURING: 1JUB076**

Vinnumber:	<b>WBA3K11000F838177</b>	Versionname:	<b>2.0 318D (100KW) TOURING</b>
First Registrationdate:	<b>25/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>96601</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4708</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>653,78</b>
-------------------	---------------

Door R R, Scratch(es), 67 - Polish	<b>0,00</b>
------------------------------------	-------------

*No pictures to display*

Bumper F, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), 67 - Polish 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Seatbelt buckle R M, Broken, E - Replace 10,00



Door F L, Scratch(es), 67 - Polish 0,00





Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing R L, Scratch(es), 67 - Polish	0,00
------------------------------------	------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*