



**BMW 5: 1JGF475**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WBA5E31000D786749</b> | Versionname: | <b>5 BER 518dA 136PK Aut.</b> |
| First Registrationdate:            | <b>10/12/2014</b>        | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>156519</b>            | Power Kw:    | <b>100</b>                    |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Grey</b>                   |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Maintenance:                       | <b>1100KM</b>            | Parking lot: | <b>4118</b>                   |
| Maintenance:                       | <b>OK</b>                |              |                               |
| Battery functioning:               | <b>Yes</b>               |              |                               |
| Number of doors:                   | <b>4</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Central consol F      |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                   |
| GPS storage                    |                              | Front parking sensors |                   |
| Windows electric F             |                              | Rear parking sensors  |                   |
| Windows electric R             |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Cruise Control                 |                              |                       |                   |
| Steering wheel multifunctional |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                   |       |                         |       |                         |
|-----------------------------------|-------|-------------------------|-------|-------------------------|
| <b>225/55/17/101 W LightMetal</b> |       |                         |       |                         |
| Summer tyres:                     | Fr.L. | <b>Vredestein: 5 mm</b> | Fr.R. | <b>Vredestein: 5 mm</b> |
|                                   | Re.L. | <b>Vredestein: 5 mm</b> | Re.R. | <b>Vredestein: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1110,36</b> |
|-------------------|----------------|

|                               |             |
|-------------------------------|-------------|
| Wing R R, Dent(s), Acceptable | <b>0,00</b> |
|-------------------------------|-------------|

*No pictures to display*

|                                 |               |
|---------------------------------|---------------|
| Windscreen, Broken, E - Replace | <b>560,64</b> |
|---------------------------------|---------------|



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Rearlight R , Broken, E - Replace 132,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 302,16



Bonnet, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display