



BMW X4: 1KCY411

Vinnumber:	WBAXX110500L94249	Versionname:	2.0 XDRIVE20D (120KW) 4WD
First Registrationdate:	2/04/2015	Fiscalpower:	
Expertise Mileage:	177333	Power Kw:	120
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4608
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/50/18/100 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	328,16
--------------------------	---------------

Door R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Spoiler R, Scratch(es), Acceptable	0,00
------------------------------------	------

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display


Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Protection plate M, Deformed / Strained, E - Replace	74,00
--	-------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

