



BMW 4 GRAN COUPE: 1KBJ318

Vinnumber:	WBA4D51080D424727	Versionname:	2.0 418D (100KW) GRAN COUPE
First Registrationdate:	25/03/2015	Fiscalpower:	
Expertise Mileage:	74566	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Body color	ZWART
Transmission:	Back	Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Maintenance	16000 KM	Oil level	OK
Maintenance	OK	Parking lot	4232
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	95,00
Wing F L, Repaired, No repair	0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

