



**CITROEN C4: 1GMK932**

Vinnumber:	<b>VF7NC9HP0EY512987</b>	Versionname:	<b>C4 BER Business GPS FAP 92PK</b>
First Registrationdate:	<b>11/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>168070</b>	Power Kw:	<b>68</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2814</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>2744,90</b>
-------------------	----------------

Tailgate, Dent(s) and scratch(es), Acceptable	<b>0,00</b>
---	-------------

<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)


95,00



Rear spoiler, Chemical polution, LI - Repair and paint (complete)


115,56






Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Roof, Chemical pollution, LI - Repair and paint (complete)

0,00



Trunk lid covering R, Scratch(es), Smart repair

110,64





Roof pillar L, Dent(s), PDR - Paintless dent repair

102,60



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Roof pillar R, Dent(s), PDR - Paintless dent repair

122,40



Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Wing F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Door R L, Scratch(es), LI - Repair and paint (complete)

318,35





Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56




Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

314,08



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56

