



BMW X1: 1JAB201			
Vinnumber:	WBAVZ91070V301573	Versionname:	X1 sDrive20d Eff.Dyn.Ed.163PK
First Registrationdate:	13/11/2014	Fiscalpower:	
Expertise Mileage:	150993	Power Kw:	120
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4125
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	610,84
Wing trim R L, Scratch(es), E - Replace	84,00



Wing R L, Dent(s), LI - Repair and paint (complete)

356,20



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Scratch(es), Smart repair

64,32



Engine protective plate, Scratch(es), E - Replace

0,00



Floor covering F L, Hole, Smart repair

64,32



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper spoiler F, Scratch(es), E - Replace

42,00

