



**FORD FOCUS CLIPPER: 1TVF362**

Vinnumber:	<b>WF06XXGCC6JL34485</b>	Versionname:	
First Registrationdate:	<b>22/02/2018</b>	Fiscalpower:	<b>74</b>
Expertise Mileage:	<b>25548</b>	Power Kw:	<b>74</b>
Bodytype:	<b>Break</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1515</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>950,85</b>
Tailgate, Scratch(es), LI - Repair and paint (complete)	<b>301,68</b>



Wing R R, Bad repair, Acceptable

0,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper F, Stone chip(s), Acceptable

0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper R, Scratch(es), Smart repair

110,64



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18





Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror R complete, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	