


CITROEN GRAND C4 PICASSO: 1KHB580

Vinnumber:	VF73E9HC8FJ614853	Versionname:	1.6 E-HDI 115 MAN6 INTENSIVE
First Registrationdate:	4/05/2015	Fiscalpower:	
Expertise Mileage:	118950	Power Kw:	85
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1709
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2822,61
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	370,00



Door panel R L, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20





Floor covering F L, Hole, E - Replace

252,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rear spoiler, Dent(s), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56





Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	