



**PEUGEOT Expert: 1JFP298**

Vinnumber:	<b>VF3XDAHZ4EZ049611</b>	Versionname:	<b>EXPERT TEPEE MWB L2H1 Access 128PK</b>
First Registrationdate:	<b>4/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>65471</b>	Power Kw:	<b>94</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV30</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>9</b>		
Number head rests:	<b>9</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/60/16/99 H Steel</b>			
Summer tyres:	Fr.L. <b>Michelin: 6 mm</b>	Fr.R. <b>Michelin: 6 mm</b>	
	Re.L. <b>Michelin: 5 mm</b>	Re.R. <b>Michelin: 5 mm</b>	

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	2230,06
-------------------	---------

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Trunk door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Trunk door R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Rearlight L, Broken, E - Replace

91,50



Bumper grille, Deformed / Strained, E - Replace

30,30



Rearlight R, Broken, E - Replace

91,50



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bumper F, Scratch(es), Smart repair

140,64

Bumper L, Scratches, smart repair 110,04



Bonnet, Dent(s), LI - Repair and paint (complete) 217,56



Door F L, Dent(s), LI - Repair and paint (complete) 238,76



Interior, Dirty, Cleaning 0,00



Internal Boot Lining R, Broken, Smart repair 110,64



Ignition key, Missing, E - Replace 150,00

No pictures to display

Internal Boot Lining L, Broken, Smart repair 110,64



Protection plate M, Tear, E - Replace 74,00

