


OPEL Zafira: 1HEJ579

Vinnumber:	WOLPD9E36E2093109	Versionname:	ZAFIRA TOURER ecoFLEX Business 136PK
First Registrationdate:	1/07/2014	Fiscalpower:	
Expertise Mileage:	109041	Power Kw:	100
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4620
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 MS Steel				
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1610,95
-------------------	---------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Wheel cover R R, Scratch(es), E - Replace

30,00



Interior, Stain, Cleaning

50,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Wing R L, Dent(s), PDR - Paintless dent repair

82,80



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

358,50





Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	366,35
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display