



|                                |                                 |              |   |
|--------------------------------|---------------------------------|--------------|---|
| <b>RENAULT Trafic: 1DDA724</b> |                                 |              |   |
| Vinnumber:                     | <b>VF1FLB1DSCY443123</b>        | Versionname: | <b>TRAFIC 29 B/F L2H2 Gr.Conf.FAP(EU5)115PK</b> |
| First Registrationdate:        | <b>13/04/2012</b>               | Fiscalpower: |   |
| Expertise Mileage:             | <b>204492</b>                   | Power Kw:    | <b>84</b>                                       |
| Bodytype:                      |                                 | Body color:  | <b>White</b>                                    |
| Gearbox:                       | <b>MAN 6 VIT</b>                | Paint type:  | <b>Opaque</b>                                   |
| Transmission:                  | <b>Front</b>                    | Rims summer: | <b>Steel</b>                                    |
| Fueltype:                      | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                       |
| Battery functioning:           | <b>Yes</b>                      | Parking lot: | <b>LCV17</b>                                    |
| Number of doors:               | <b>5</b>                        |              |   |
| Number of seats:               | <b>3</b>                        |              |   |
| Number head rests:             | <b>3</b>                        |              |   |
| Rims summer:                   | <b>Steel</b>                    |              |   |
| Category:                      | <b>Light Commercial Vehicle</b> |              |   |
| Oil level:                     | <b>OK</b>                       |              |   |

|                         |                               |
|-------------------------|-------------------------------|
| <b>Options</b>          |                               |
| Radio CD                | Central consol F              |
| Windows electric F      |                               |
| Type of headlighting    | <b>Headlighting Halogen</b>   |
| Type of Lining          | <b>Lining fabrics</b>         |
| Type of climate control | <b>Manual climate control</b> |

|                                     |           |                     |               |
|-------------------------------------|-----------|---------------------|---------------|
| <b>Limited Technical Inspection</b> |           |                     |               |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>     |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>NOT OK</b> |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                                     |           | Lighting            | <b>OK</b>     |
|                                     |           | Wiperblades         | <b>OK</b>     |

|                       |                              |                          |       |                       |
|-----------------------|------------------------------|--------------------------|-------|-----------------------|
| <b>Degree of wear</b> |                              |                          |       |                       |
|                       | <b>215/65/16/109 C Steel</b> |                          |       |                       |
| Summer tyres:         | Fr.L.                        | <b>Michelin: 4 mm</b>    | Fr.R. | <b>Michelin: 4 mm</b> |
|                       | Re.L.                        | <b>Continental: 3 mm</b> | Re.R. | <b>Dunlop: 1 mm</b>   |

|                             |           |
|-----------------------------|-----------|
| <b>Assistance equipment</b> |           |
| Spare wheel                 | <b>No</b> |

|  |         |
|--|---------|
| Total cost ex VAT                              | 2855,35 |
| De-icer nozzle internal R, Broken, E - Replace | 153,00  |



|   |        |
|---|--------|
| Rocker panel inner F L, Scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>                   |        |
| Air vent mid-dashboard, Broken, E - Replace     | 153,00 |



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

334,76



Bodywork, Not original part, Acceptable

0,00

*No pictures to display*

Door moulding Lower R R, Scratch(es), E - Replace

91,50



Ignition key, Missing, E - Replace

150,00



Seat cover F L, Tear, E - Replace

300,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00

*No pictures to display*

Interior, Worn, Acceptable

0,00

*No pictures to display*

Trunk door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Steering wheel, Worn, Acceptable

0,00

*No pictures to display*

Wing trim R R, Scratch(es), E - Replace

69,00



Spare wheel, Missing, E - Replace

153,60



Side window trim R R, Missing, E - Replace

10,80



Wing R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Tyre R R, Worn, E - Replace

105,00



Wheel cover R L, Missing, E - Replace

22,50



Bumper corner R L, Scratch(es), Smart repair

110,64



Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

334,00



Bumper F, Dent(s) and scratch(es), E - Replace

398,40





Engine, Maintenance, Execute

0,00

