



RENAULT Grand Espace: 1GHS474

Vinnumber:	VF1JKFHC650358334	Versionname:	GR.ESPACE Business 130PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	184589	Power Kw:	96
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2632
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

225/55/17/101 Y LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Uniroyal: 4 mm
	Re.L.	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	1475,43
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s), PDR - Paintless dent repair	82,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21



Door F L, Scratch(es), Acceptable

0,00

No pictures to display


Wing R R, Scratch(es), LI - Repair and paint (complete)

369,84



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Bonnet, Dent(s), PDR - Paintless dent repair

122,40

