


**SKODA OCTAVIA COMBI: 1LNE920**

Vinnumber:	<b>TMBLG7NE6G0100944</b>	Versionname:	<b>1.6 CRTDI 81KW 4WD GREENTEC AMBITION</b>
First Registrationdate:	<b>27/10/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>187192</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>NU UITVOEREN</b>	Parking lot:	<b>2610</b>
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 1768,85

Wheel cover R R, Scratch(es), E - Replace 30,00



Sill outer R, Dent(s), LI - Repair and paint (complete)

454,50



Rear roof pillar covering L, Scratch(es), E - Replace

70,00



Mats, Missing, E - Replace

50,00



Windscreen, Broken, E - Replace

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20



Wheel cover F L, Scratch(es), E - Replace

30,00



Wheel cover F R, Scratch(es), E - Replace

30,00



Maintenance - Maintenance - Execute

0,00




Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Interior, Dirty, Cleaning

100,00



Rear roof pillar covering R, Scratch(es), E - Replace

70,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display