



VOLKSWAGEN Golf: 1HNG326

Vinnumber:	WVWZZZAUZFP011211	Versionname:	GOLF BER Highline 105PK
First Registrationdate:	27/08/2014	Fiscalpower:	
Expertise Mileage:	96356	Power Kw:	77
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4719
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	423,60
Bonnet, Chemical polution, LI - Repair and paint (complete)	0,00




Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Roof, Chemical polution, LI - Repair and paint (complete)

0,00




Maintenance book, Missing, E - Replace

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display