



VOLKSWAGEN Caddy: 1GRA655

Vinnumber:	WV1ZZZ2KZEX115538	Versionname:	CADDY MAXI VAN B/F 102PK
First Registrationdate:	4/04/2014	Fiscalpower:	
Expertise Mileage:	118349	Power Kw:	75
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3613
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Type of Tow bar	Tow bar fixed
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/95 H Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1348,05
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Rearlight R , Broken, E - Replace	91,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 327,15



Sliding door R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), Le - Replace and paint 546,00



Bumper R, Scratch(es), E - Replace 329,40



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 54,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display