



VOLVO V40: 1HNC718

Vinnumber:	YV1MV8481F2190482	Versionname:	V40 D2 Base 115PK
First Registrationdate:	26/08/2014	Fiscalpower:	
Expertise Mileage:	191736	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2714
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 6 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 581,60

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Chemical polution, LI - Repair and paint (complete) 211,80



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable 0,00

No pictures to display