



VOLVO V40 CROSS COUNTRY: 1KCL131

Vinnumber:	YV1MZ8451F2076655	Versionname:	1.6 D2 KINETIC
First Registrationdate:	1/04/2015	Fiscalpower:	
Expertise Mileage:	90718	Power Kw:	84
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 7118 KM	Parking lot:	1507
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/92 V LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	477,12
-------------------	---------------

Wing F R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof pillar R, Dent(s), PDR - Paintless dent repair 63,00



Door R R, Dent(s), It - Spot repair 115,56



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Bumper F, Bad repair, Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Paintless dent repair 63,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Interior, Dirty, Cleaning 25,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Dent(s), It - Spot repair 115,56

