



VOLVO V40: 1KNP746

Vinnumber:	YV1MV8481F2249158	Versionname:	1.6 D2 VOLVO OCEAN RACE
First Registrationdate:	3/06/2015	Fiscalpower:	
Expertise Mileage:	133673	Power Kw:	84
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/93 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	3534,48
Internal Boot Lining R, Broken, E - Replace	72,52



Mirror side blinker R, Scratch(es), E - Replace

30,00



Grill, Broken, E - Replace

32,40



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Centre console, Scratch(es), Smart repair

110,64



Trunk lid covering R, Scratch(es), Smart repair

110,64



Seat cover F R, Scratch(es), Smart repair

64,32



Centre console, Glue residues, Smart repair

110,64



Bumper F, Dent(s) and scratch(es), LI - Replace and paint

735,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille, Broken, E - Replace

32,40



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), PDR - Paintless dent repair

63,00



Bumper moulding R, Scratch(es), Smart repair

110,64

No pictures to display

Front end, Deformed / Strained, P - Check

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

356,20



Rearview mirror L complete, Broken, E - Replace

168,00



Bumper grille, Broken, E - Replace

32,40



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Broken, E - Replace

240,00



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Ceiling, Hole, E - Replace

494,00



Backrest cover R M, Scratch(es), Smart repair

64,32



Rearlight L, Scratch(es), 67 - Polish

0,00

No pictures to display

Sill outer R, Scratch(es), It - Spot repair

115,56

