


PEUGEOT 208: 1NGJ619

Vinnumber:	VF3CC8HY6FT175009	Versionname:	1.6 BLUEHDI 74KW S/S 79G ALLURE
First Registrationdate:	18/02/2016	Fiscalpower:	
Expertise Mileage:	203321	Power Kw:	74
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:		Oil level:	OK
Battery functioning:	Yes	Parking lot:	1728
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Panoramic roof
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/55/16/87 H LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	887,84
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 232,06



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Ignition key, Missing, E - Replace 150,00

No pictures to display