



**TOYOTA Auris: 1GPP429**

|                                    |                          |              |  |
|------------------------------------|--------------------------|--------------|--|
| Vinnumber:                         | <b>SB1MS3JE00E067891</b> | Versionname: | <b>AURIS BER HSD Hybr.Lounge CVT 99PK Aut.</b> |
| First Registrationdate:            | <b>26/03/2014</b>        | Fiscalpower: |  |
| Expertise Mileage:                 | <b>84840</b>             | Power Kw:    | <b>73</b>                                      |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                                   |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                                 |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                               |
| Fueltype:                          | <b>Hybrid Petrol</b>     | Oil level:   | <b>OK</b>                                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3127</b>                                    |
| Number of doors:                   | <b>5</b>                 |              |  |
| Number of seats:                   | <b>5</b>                 |              |  |
| Number head rests:                 | <b>5</b>                 |              |  |
| Rims summer:                       | <b>Aluminium</b>         |              |  |
| Category:                          | <b>Passenger Car</b>     |              |  |
| Oil level:                         | <b>OK</b>                |              |  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |  |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Panoramic roof        |                   |
| GPS storage                    |                              | Central consol F      |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover         |                   |
| Windows electric F             |                              | Front parking sensors |                   |
| Windows electric R             |                              | Rear parking sensors  |                   |
| Cruise Control                 |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Steering wheel multifunctional |                              |                       |                   |
| Seats F heated                 |                              |                       |                   |
| Radio multimedia               |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining semi-leather</b>   |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                          |       |                          |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| <b>225/45/17/91 W LightMetal</b> |       |                          |       |                          |
| Summer tyres:                    | Fr.L. | <b>Dunlop: 4 mm</b>      | Fr.R. | <b>Dunlop: 4 mm</b>      |
|                                  | Re.L. | <b>Continental: 5 mm</b> | Re.R. | <b>Continental: 5 mm</b> |

**Assistance equipment**

|  |            |            |            |
|--|------------|------------|------------|
| Repair kit                               | <b>Yes</b> | Compressor | <b>Yes</b> |
| Number of charging cables (normal)       | <b>0</b>   | Jack       | <b>Yes</b> |
| Number of charging cables (rapid charge) | <b>0</b>   |            |            |

Total cost ex VAT 2313,71

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Internal Boot Lining R, Hole, E - Replace

20,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof pillar L, Dent(s), PDR - Paintless dent repair

63,00



Mirror side blinker R, Broken, E - Replace

30,00



Tyre F R, Tear, E - Replace

132,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35







Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Bonnet, Stone chip(s), Acceptable

0,00



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display