



VOLVO V40: 1KCH786			
Vinnumber:	YV1MVA851F2242292	Versionname:	2.0 D4-85 SUMMUM R-DESIGN
First Registrationdate:	31/03/2015	Fiscalpower:	
Expertise Mileage:	115819	Power Kw:	140
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3729
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1152,13
--------------------------	----------------

Rearview mirror housing L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display	
Door F R, Scratch(es), Acceptable	0,00

No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

