



**NISSAN Qashqai: 1HFG298**

Vinnumber:	<b>SJNFAAJ11U1132104</b>	Versionname:	<b>QASHQAI 2WD Tekna 110PK</b>
First Registrationdate:	<b>7/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>129788</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4104</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage		Panoramic roof	
GPS storage	<b>SD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/45/19/92 W LightMetal</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 8 mm</b>	Fr.R.	<b>Uniroyal: 8 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

**Assistance equipment**

Compressor	<b>Yes</b>
------------	------------

Total cost ex VAT	<b>491,68</b>
-------------------	---------------

Door R R, Dent(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

*No pictures to display*

Wing F L, Dent(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

*No pictures to display*

Tailgate, Scratch(es), LI - Repair and paint (complete)	<b>301,68</b>
---	---------------



Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

