



VOLKSWAGEN GOLF VII: 1LNE918

Vinnumber:	WVWZZZAUZGP052021	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	27/10/2015	Fiscalpower:	
Expertise Mileage:	180564	Power Kw:	81
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1ST VERDIEP STEENTJES
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	540,26
-------------------	---------------

Door R R, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Seat cover F R, Dirty, Cleaning	25,00
---------------------------------	--------------



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), It - Spot repair 115,56



Seat cover F L, Dirty, Cleaning 25,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk lid covering R, Broken, E - Replace 99,90



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Acceptable 0,00

No pictures to display