



RENAULT Megane: 1HJK329

Vinnumber:	VF1KZ140651160520	Versionname:	MEGANE BRE Energy GT-Line 110PK
First Registrationdate:	1/08/2014	Fiscalpower:	
Expertise Mileage:	91491	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4307
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/89 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1871,03
Floor covering F L, Damaged, E - Replace	84,00



Ignition key, Missing, E - Replace

150,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door R L, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), Le - Replace and paint

0,00



Bumper grille F R, Deformed / Strained, E - Replace

0,00



Interior, Dirty, Cleaning

75,00





Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Bumper F, Deformed / Strained, Le - Replace and paint 0,00



Wing F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Headlight R, Scratch(es), E - Replace 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper spoiler F, Scratch(es), E - Replace 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Deformed / Strained, E - Replace 0,00



Grill frame, Broken, E - Replace 0,00



Bumper grille F L, Scratch(es), E - Replace 74,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front end, Crack, Le - Replace and paint 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Wing F R, Deformed / Strained, Le - Replace and paint 0,00

