



BMW X4: 1KUY475			
Vinnumber:	WBAXW110600P38349	Versionname:	2.0 XDRIVE20I AUTO 4WD
First Registrationdate:	9/07/2015	Fiscalpower:	
Expertise Mileage:	113029	Power Kw:	135
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1410
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	275/40/19/101 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT		2928,45
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00



Wheel arch cover R R, Scratch(es), E - Replace 124,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wheel arch cover F R, Scratch(es), E - Replace 124,00



Wheel arch cover F L, Scratch(es), E - Replace 124,00



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Ignition key, Missing, E - Replace 150,00

No pictures to display