



VOLVO V60: 1HEG560

Vinnumber:	YV1FW73CDF1224359	Versionname:	V60 BRE D4 Kinetic Geartr.181PK Aut.
First Registrationdate:	1/07/2014	Fiscalpower:	
Expertise Mileage:	138410	Power Kw:	133
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3413
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar removable
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/92 H LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			786,92
Rocker panel inner F L, Scratch(es), Repair/replace (lump sum)			115,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Repaired, Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), It - Spot repair

115,56



Door R L, Dent(s), It - Spot repair

115,56



Door panel F L, Scratch(es), E - Replace

114,00



Rocker panel inner R L, Scratch(es), Repair/replace (lump sum)

115,00

