



**FORD FOCUS: 1KLE274**

Vinnumber:	<b>WF05XXGCC5FD02648</b>	Versionname:	<b>1.5 TDCI 77KW S/S ECON 88G BUSINESS ED</b>
First Registrationdate:	<b>26/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>40374</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3523</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 H Steel</b>				
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>870,50</b>
Seat cover F L, Stain, Cleaning			<b>25,00</b>



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), 67 - Polish 0,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door R R, Bad repair, LI - Repair and paint (complete) 318,35



Tires, Out of tolerance, P - Check 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Engine protective plate, Hole, E - Replace 58,80

