



**FORD FOCUS: 1HJR632**

Vinnumber:	<b>WF06XXGCC6JY59424</b>	Versionname:	
First Registrationdate:	<b>19/03/2018</b>	Fiscalpower:	<b>88</b>
Expertise Mileage:	<b>38298</b>	Power Kw:	<b>Black</b>
Bodytype:	<b>Break</b>	Body color:	<b>Metalic</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Aluminium</b>
Transmission:	<b>Front</b>	Rims summer:	<b>OK</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>1222</b>
Battery functioning:	<b>Yes</b>	Parking lot:	
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/94 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Goodyear: 7 mm</b>	Re.R.	<b>Goodyear: 7 mm</b>


**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>885,59</b>
Tailgate, Scratch(es), LI - Repair and paint (complete)	<b>301,68</b>



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F M, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35



Bumper corner R L, Scratch(es), It - Spot repair	115,56
--	--------



Wing F L, Bad repair, Acceptable	0,00
----------------------------------	------

*No pictures to display*