



**VOLKSWAGEN PASSAT VARIANT: 1WJX974**

Vinnumber:	<b>WVWZZZ3CZGE144883</b>	Versionname:	<b>2.0 TDI MSQ VARIANT HIGHLINE</b>
First Registrationdate:	<b>30/12/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>97262</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>STEENTJES</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Sun Roof electric	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather and alcantara</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/17/94 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Michelin: 1 mm</b>	Fr.R.	<b>Michelin: 1 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

Total cost ex VAT	<b>724,50</b>
Sill outer R, Scratch(es), LI - Repair and paint (complete)	<b>310,50</b>



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

*No pictures to display*

Seat cover F L, Deformed / Strained, Acceptable	0,00
---	------

*No pictures to display*

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

*No pictures to display*

Door panel F R, Burned, E - Replace	114,00
-------------------------------------	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*